

Nº 5304

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-5-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 513'

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 158'

7' deep

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

6TH ST. S.W.



N →

7' deep

8'

158'

4"

SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

8-11-49

REMARKS:

Relaid job.

Nº 5304

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/1

1949

RECEIVED OF J. Black

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED same

TO TAP San

SEWER, ON THE W.

SIDE

OF 6th St W

AVE., TYPE OF STREET Paved

THE PREMISES BEING LOT NO. 1863

HOUSE NO. 513

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations. Relief