Nº 5306

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8 - 6 - 4	# IF SO HOW AND LOCATION FROM	
	FIRST MANHOLE DOWN STREAM	
HOUSE NO		,
710002 110.	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	· · · · · · · · · · · · · · · · · · ·
WAS LATERAL AT CURB? 🗡 💆 💲	<u> </u>	
Augustin Committee Committ	EL ALL	17
WAS ATTACHED TO MAIN 🚅 🦭 🥌	_ NAME OF CONTRACTOR EX Alb	recht
SHOW BY DIAGRAM RELATION OF L	ATERAL TO WALL OF BUILDING SERVED.	
29年	st, N.W.	
		7:400
		, <i>j</i>
	N	
		· · · · · · · · · · · · · · · · · · ·
•		2 - 6/00/
	Transmitter of the Control of the Co	anna ann an a
e e e e e e e e e e e e e e e e e e e	And the second s	
A Start		
SIGNED The Lite	FILED AT ENGINEER'S OFFICE	8-11-49
INSPECTOR FOR	SITY	
REMARKS:		
REMARNS:		Tanana and the same and the sam

Nº 5306

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillon, Ohigo	2/2	
RECEIVED OF Atham	Make	FEE OF \$2	
OR WHICH PERMISSION IS GRANTED ATA	un Ouk	٤	
O TAP Sanitary SEW	/ER, ON THE	last.	SIDE
, 29 11 hH. AVE. T	YPE OF STREET	ilou	
HE PREMISES BEING LOT NO. 237	, House No	732	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND

NAME OF CONTRACTOR E.K. Whole cht

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.