Nº 5313

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-16-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	9. dech
HOUSE NO. 950	-/-	· ·
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? No		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR BOGET,	
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING SERVED.	
17th ST. N.E		2 10
	5 deep	0
	9 deep	, i
A		1101 23
SIGNED I Am Ehra	FILED AT ENGINEER'S OFFICE_	8 ch stream
INSPECTOR FOR CITY	, , , , , , , , , , , , , , , , , , , ,	The same of the sa
REMARKS: Tapped 12	malh,	and the second

Nº 5313

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

			M	ASSILLON, OHIO,	9/12	19
	RECEIVED OF	_ Tank	Chale	man)_	FEE OF \$	
			andre	garan en	. The second	
FOR	WHICH PERMIS	SION IS GRANTED				
тот	TAP	Land	SEWER, ON	N THE		
OF_	17t	a nE	AVE. TYPE O	F STREET CO	led	
, <u> </u>		1	1171		657	
		G LOT NO	/ 6	, House No	100	

13000

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.

دد