## Nº 5315

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-27-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED 6"  WAS LATERAL AT CURB? Yes	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	5.6" dech
WAS ATTACHED TO MAIN Vestion of LAT	NAME OF CONTRACTOR ALbrecht, ERAL TO WALL OF BUILDING SERVED.	
18## 5T, N.		7 deg
guen su novembre de municipalista de manda de m	35.	5'60
	0	
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	The But But he had been been been been been been been bee

## Nº 5315

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	87-4
Massillon, Ohio,	1947
RECEIVED OF E.K. allnecht	FEE OF \$2
Ralph Ross	
FOR WHICH PERMISSION IS GRANTED	
TO TAP Santary SEWER, ON THE	west side
OF BULL DE AVE. TYPE OF STREET	vilon
THE PREMISES BEING LOT NO 1066 4 9067 1/2 HOUSE NO_	403
THE PREMISES BEING LOT NO. 7066 4 4 66 / 2	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323. DULY PAS	SED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	

NAME OF CONTRACTOR 2. K. Alleght

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.