## 5316

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-25-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT 150 TO 6 TO
WAS LATERAL AT CURB? / 15	A I I suffer
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR A Brecht
SHOW BI DIAGRAM RELATION OF EAT	PIVATIO MATERIAL STATES
16 Els 5 to N.	E
<b>N</b>	7'bech
que no mandre con mentre por la companya de la comp	an a commencation of the contract of the contr
	7'beat 2 130'
SIGNED JOHN INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE 9-3-47
REMARKS:	

## Nº 5316

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillon, Oh	110, 8/24	1947
RECEIVED OF E.K. al	loudt	FEE OF \$\mathcal{E}	2 00
OR WHICH PERMISSION IS GRANTED	all the state of t	last	
OTAP Dunitary	_SEWER, ON THE	west	SIDE
or 16 M E AV	E. TYPE OF STREET	pana	·
HE PREMISES BEING LOT NO. 5795	, Hous	9/0	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND

NAME OF CONTRACTOR & R. allricht

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.