Nº 5317

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| FII | F SO HOW AND LOCATION FROM IRST MANHOLE DOWN STREAM |
|--|--|
| CIZE OF BIRE USED 4" DO | OWN STREAM TO DITCH AT 299 5' dech |
| WAS LATERAL AT CURB? Yes | NAME OF CONTRACTOR Diana |
| WAS ATTACHED TO MAIN VES N. SHOW BY DIAGRAM RELATION OF LATERA | AL TO WALL OF BUILDING SERVED. |
| Cambell Circl | 4 4 def |
| | 7 299 |
| 1 1 5 | |
| SIGNED INSPECTOR FOR CITY | FILED AT ENGINEER'S OFFICE |

Nº 5317

PERMIT TO TAP SEWER

| | | · | | |
|--------------------------------|----------------|----------|--------------------|------|
| RECEIVED OF | MASSILLON | , Оніо, | 72.5 FEE OF \$2 | 949 |
| OR WHICH PERMISSION IS GRANTED | ale t | any be | ll | |
| O TAP Canitary | _SEWER, ON THE | 1 1 | vest | SIDE |
| Panyhell li letavi | P | pan | ud | 51DE |
| HE PREMISES BEING LOT NO. 592 | . | OUSE NO. | 47 | |
| | · · | | | |

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, an Rules of the Department of Public Service.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.