Nº 5321

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $9-30-49$	IF SO HOW AND LOCATION FROM FIRST MANHOLE REPORT STREAM	28'	12'dech
HOUSE NO. 50			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?		•	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	remley.	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SE	RVED.	
Charles.A	vc.S.E.	*	
	1	1/0	8.40%
	2	The state of the s	0
			12 200
SIGNED John Ehm	EU ED AT ENGL	ITEMS OFFICE	vh Stream.
INSPECTOR FOR CITY	FILED AT ENGIN	TEER'S OFFICE	
REMARKS: Tapped 1	n main.		

Nº 5321

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Atta			61	£~*
	and the second s	Massil	LON, OHIO,	<u>, // 1 </u>	194/
	naule	Dad 7	1 / / / / / / / / / / / / / / / / / / /	FEE OF \$	2 44
RECEIVED OF			Odd:	4.	Assa
FOR WHICH PERMISSION	ON IS GRANTED		(* Se an don't		
TO TAP Sun	tune	_SEWER, ON THE			SIDE
2 Lode	ande		REET	and de	
) / 2	T.,	. House No.	30	
THE PREMISES BEING I	LOT NO.		,		

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND

NAME OF CONTRACTOR Approved Runley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.