Nº 5322

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 9-14-49 IF SO HOW AND LOCATION FROM 19 1 deals |
|---|
| HOUSE NO |
| SIZE OF PIPE USED DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH |
| WAS LATERAL AT CURB? |
| WAS ATTACHED TO MAIN NAME OF CONTRACTOR DE/VEAL |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. |
| 2380 ST. N.W. |
| |
| |
| C N |
| |
| |
| 273. 3\19deep |
| SIGNED OF THE STATE OF SIGNET 9-14-49 |
| SIGNED FILED AT ENGINEER'S OFFICE |
| REMARKS: |

Nº 5322

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

| | MASSILLON, OHIO. 9-6 1949 |
|---|--|
| RECEIVED OF FAUL DOEP | |
| FOR WHICH PERMISSION IS GRANTED Deluc | a Constr. Co. |
| OTAP Sanitary SEWER | ON THE FOST SIDE |
| | E OF STREET GROVE |
| HE PREMISES BEING LOT NO. 5976 | House No. 162 |
| | |
| Nork to be done in accordance with Ordinanc Rules of the Department of Public Service. | E No. 2323. DULY PASSED BY THE CITY COUNCIL, AND |

NAME OF CONTRACTOR Deluca Gosti 6.

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.