

Nº 5323

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

14
48

DATE INSPECTED 9-14-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

238' ? 9' deep

HOUSE NO. 158

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR DeLuca

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

23 RD ST. NW.



SIGNED

John E. Chmura
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-14-49

REMARKS: _____

Nº 5323

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5-6 194

RECEIVED OF Paul Doering FEE OF \$

FOR WHICH PERMISSION IS GRANTED Deluca Constr. Company

TO TAP Sanitary SEWER, ON THE East SIDE

OF 73rd St. N.W. AVE., TYPE OF STREET Gravel
ST.,

THE PREMISES BEING LOT NO. 5977 HOUSE NO. 158

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Deluca Constr. Co.

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.