## Nº 5325

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF	LATERAL TO WALL OF BUILDING SERVED.
OH10. 3T.	N. W.
	N 34.00
•	
. 4	85
SIGNED INSPECTOR FOR	N. END. Trunk. Talhed in
DEMARKS.	

Nº 5325

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

9.800	e de la companya de La companya de la co		Massillon, Ohio	9-7	194
RECEIVED	OF FRAD	Schra	der	FEE (	2 °°
FOR WHICH PE		TEN YE F	molece		
TO TAP	anitar	SEWI	ER ON THE	orth	SIDE
	hio Ave	NO AVE. T	PE OF STREET	Pirt	3,00
THE PREMISES (		1988	, House	No. 14	· · · · · · · · · · · · · · · · · · ·
			ICE No. 2323. DULY	PASSED BY THE C	CITY COUNCIL, AND
RULES OF THE	DEPARTMENT OF P	UBLIC SERVICE.			
Name of Cont	RACTOR R.	emleg		<u> </u>	
Note.	This permit	covers work	outside of build	ling only. An	y work inside

walls of building is subject to Massillon Board of Health Regulations.

7