

14-50 - C

Nº 5329

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-1-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1900

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
TO DITCH AT
CURB LINE AND DEPTH

17'

8' deep


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Woodruff Ave N.W.



SIGNED John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Nº 5329

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO.

9-7

1949

RECEIVED OF

Florence Arnold

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

R Remley

TO TAP

San

SEWER, ON THE

N.

SIDE

OF

Woodruff NW.

AVE.,
ST.,

TYPE OF STREET

Dist

THE PREMISES BEING LOT NO.

4903

HOUSE NO.

1900

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.