

Nº 5336

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

13

DATE INSPECTED 5-14-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 302

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED 4"


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

8TH ST. S.W.



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-13-49

REMARKS:

Relaid job

Nº 5336

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

7-9

194

RECEIVED OF

Repair

Isabel L. Walrath

FEE OF \$

2⁰⁰

FOR WHICH PERMISSION IS GRANTED

Raymond Remley

TO TAP

Sanitary

SEWER, ON THE

East

SIDE

OF

8th St. S.W.

AVE.,
ST.,

TYPE OF STREET

Dirt

THE PREMISES BEING LOT NO.

3613

HOUSE NO.

302

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. Remley

Note. This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health Regulations.