

Nº 5337

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

9
5-8
✓

DATE INSPECTED 5-25-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

45'

8' deep

HOUSE NO. 2872

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way W.



SIGNED

John E. Hume
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-13-49

REMARKS:

Relaid old line

Nº 5337

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Repair

MASSILLON, OHIO,

9-7

194*9*

RECEIVED OF

Charles Conklin

FEE OF \$

2⁰⁰

FOR WHICH PERMISSION IS GRANTED

Raymond Remley

TO TAP

Sanitary

SEWER, ON THE

North

SIDE

OF

Lincoln Way NW

AVE.,
ST.,

TYPE OF STREET

Brick

THE PREMISES BEING LOT NO.

986

HOUSE NO.

2872

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.