

Nº 5338

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

7
8
1

DATE INSPECTED 8-9-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 150 5' deep

HOUSE NO. 2519

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way. W.



SIGNED John H. Hauer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-13-49

REMARKS: _____

Nº 5338

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

9-7

1947

RECEIVED OF

Jacob Sanders

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Raymond Remley

TO TAP

Sanitary

SEWER, ON THE

South

SIDE

OF

Lincoln Way N.W.

AVE.,
ST.,

TYPE OF STREET

Brick

THE PREMISES BEING LOT NO.

8667

HOUSE NO.

2519

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.