

Nº 5339

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-3-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____


NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Erie St. S.

N. →



SIGNED

John E. Chamer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-13-49

REMARKS:

Relaid job.

Nº 5339

Repair

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

194

RECEIVED OF

Brown Lumber Co.

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Raymond Remley

TO TAP

Sanitary

SEWER, ON THE

West

SIDE

OF

Eric St. So.

AVE.,
ST.,

TYPE OF STREET

Asphalt

THE PREMISES BEING LOT NO.

O.L. 39

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.