

Nº 5346

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

14
48
✓

DATE INSPECTED 9-14-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

74'

10' deep

HOUSE NO. 204

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Deluca

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

23 RD ST. N.W.



SIGNED

John Chinner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9/14/49

REMARKS: _____

Nº 5346

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/10

194

RECEIVED OF

Ella Fadden

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Drain

TO TAP

San

SEWER, ON THE

E.

SIDE

OF

23rd NW

AVE.,
ST.

TYPE OF STREET

Alley

THE PREMISES BEING LOT NO.

5972

HOUSE NO.

204

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

De Luca

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.