## Nº 5347

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-13-49	IF SO HOW AND LOCATION FROM		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOL DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	.e 83'	7. dach
WAS LATERAL AT CURB? YRS	NAME OF CONTRACTOR	Diana	
SHOW BY DIAGRAM RELATION OF LATE	ERAL TO WALL OF BUILDING	G SERVED.	
3 RD ST. N.	ikun -		E'deep
	madestrong and morrough con-	ormanistration communication and the communi	2/2/16 cch
SIGNED JOHN INSPECTOR FOR CITY	FILED AT E	INGINEER'S OFFICE	2-28-49-20-20-20-20-20-20-20-20-20-20-20-20-20-
REMARKS:			

## . Nº 5347

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

			1	
	MASSILLON,	Оню	//3	_194/
RECEIVED OF	ana		. FEE OF \$	<u> </u>
FOR WHICH PERMISSION IS GRANTED	nla	Roan	- -	
FOR WHICH FERMISSION IS GRANTED				
TO TAP Same tang SEW	ER, ON THE	- And	+.	side
of 3 70 11 n. E. AVE T	YPE OF STREET.	100	ba_	
THE PREMISES BEING LOT NO. 77/5		ouse No. / 6	3/	
WORK TO BE DONE IN ACCORDANCE WITH ORDINA	NCE NO. 2323.	DULY PASSED BY	THE CITY COU	NCIL, AND

CULES OF THE DEPARTMENT OF PUBLIC SERVICE.

AME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.