## Nº 5354

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-20-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	122	7: doch
WAS LATERAL AT CURB?	,		
WAS ATTACHED TO MAIN 765	NAME OF CONTRACTOR	570n	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING SE	RVED.	
Walnut Rd.	5.40.	4	
en e			
	2	14	122 J
		and particular of the second seco	and the second resident and an analysis of the second second second second second second second
	Managara Ma	And the second s	and the second s
SIGNED John Chri	FILED AT ENGI	NER'S OFFICE	9-23
INSPECTOR FOR CITY			
REMARKS:			

## Nº 5354

## PERMIT TO TAP SEWER

•			the property of the second	
		MASSILLON, OHIO,	1/19	_194/
		1	3	v Ž
RECEIVED OF	med !	Molin	FEE OF \$	
FOR WHICH PERMISSION IS GRANTE	Ollan	Frank	an	
FOR WHICH PERMISSION IS GRANTE			2)	
TO TAP Lamila	sewer	r, ON THE	south	SIDE
or Halmet Ra	11	E OF STREET	oilea	
THE PREMISES BEING LOT NO	3110	, House No	952	-
Work to be done in accordance	E WITH ORDINANC	E No. 2323. DULY PA	SSED BY THE CITY COU	NCIL, AND
RULES OF THE DEPARTMENT OF PU	BLIC SERVICE.			
NAME OF CONTRACTOR 2	ston			

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.