

Nº 5361

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

$\frac{7}{39}$

DATE INSPECTED 9-27-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 15

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 14' 6' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Aston.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

23 RD ST. N.W.



SIGNED

John E. Chesser
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-27-49

REMARKS: _____

Nº 5361

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/26 1949

RECEIVED OF J. Aston

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Verdum Skalmitch

TO TAP San

SEWER, ON THE W

SIDE

OF 23rd St

AVE.,
ST.,

TYPE OF STREET Dist

THE PREMISES BEING LOT NO. 3749

HOUSE NO. 15

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Aston

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.