

Nº 5362

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-29-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2238

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

5' 8" deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

23 RD ST. N.W.

← N



SIGNED

John Chmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-29-49

REMARKS:

Nº 5362

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/26 1948

RECEIVED OF J. L. Aston

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Barrel Kerr

TO TAP San

SEWER, ON THE D

SIDE

OF Courtland NW

AVE. TYPE OF STREET dent
ST.

THE PREMISES BEING LOT NO. 5983

HOUSE NO. 2238

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Aston

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.