

Nº 5370

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

14
28
1

DATE INSPECTED 10-26-49

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 161~ 7' deep

HOUSE NO. 724 1/2 Rear

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____



WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Albrecht

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

32ND ST. N. W.



SIGNED John E. Egan

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 161' Tapped in

REMARKS: _____

Nº 5370

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO.

1949

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

SIDE

OF

AVE.,
ST.,

TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.