## Nº 5376

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED //-/2-49	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 828	DISTANCE FROM FIRST MANHOLE		
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		9' Deep
WAS LATERAL AT CURB? YES	•	Albrecht	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	///	
SHOW BY DIAGRAM RELATION OF LATE	L' Deep Side	wolk is on C Line of Walk. n Sewer in L	orb Line
SIGNED INSPECTOR FOR CITY	filed at ENG	INEER'S OFFICE	19-99
REMARKS:	<b>∀</b>	on the contract of the children with the children of the child	

Nº 5376

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillon, O	1/0	194
RECEIVED OF	2 alkred	FEE OF \$	700
FOR WHICH PERMISSION IS GRANTED	Orald 2	Cherry	
TO TAP	SEWER, ON THE	474	SIDE
Lebo 718	AVE. TYPE OF STREET_	02020	
THE PREMISES BEING LOT NO.	13	se No. 828	
WORK TO BE DONE IN ACCORDANCE			Council, AND
RULES OF THE DEPARTMENT OF PUBL			

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.