

7-9-12 ✓

Nº 5378

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 11-26-49 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 10' 7' dca

HOUSE NO. 1507

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB?_____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR Remick

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way E.



SIGNED

John E. Turner
INSPECTOR FOR CITY

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12-23-49

REMARKS:

Relaid job.

Relay
Nº 5378

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

1949

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

SIDE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health Regulations.