

Nº 5381

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

9-13-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

1420

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
~~GRADE~~ LINE AND DEPTH

113'

7' Deep

WAS LATERAL AT CURB?

Yes

Walk


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Keuper

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N ←



Lateral had been
previously run in to back
edge of side walk.

7' Deep at back edge of walk.
Side walk
E. Curb.
Main Sewer

SIGNED

R. J. Chrysler

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10-2-50

REMARKS:

Inside City Limits

Nº 5381

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

1949

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

SIDE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.