FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED Nº 5382 DATE INSPECTED 9-11-52 FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH SIZE OF PIPE USED WAS LATERAL AT CURB? NAME OF CONTRACTOR KEV SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. Janice Ave N.E.

REMARKS

Nº 5382

PERMIT TO TAP SEWER

Massillon, Ohio,	194
RECEIVED OF COLOR OF	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	
TO TAPSEWER, ON THE	SIDE
OF AVE TYPE OF STREET	1
THE PREMISES BEING LOT NO	142
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSE RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	ED BY THE CITY COUNCIL, AND

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.