

Nº 5394

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

11
22

DATE INSPECTED 3-8-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 19' 12' deep

HOUSE NO. 953

SIZE OF PIPE USED 6

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 21 8' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

27' 11" SW. N.W.



SIGNED John Thuermer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 3-30-50

REMARKS: _____

Nº 5394

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 2/16 1950

RECEIVED OF

A. J. Diana

FEE OF

2⁰⁰

FOR WHICH PERMISSION IS GRANTED

Harry Bonto

TO TAP

sanitary

SEWER, ON THE

west

SIDE

OF

27th H H
outside coop. line

AVE.,
ST.

TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

331

HOUSE NO.

353

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

A. J. Diana

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.