

Nº 5398

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

C
✓

DATE INSPECTED 4-7-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1021

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Benington Ave NE.



SIGNED

John Chamer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

4-4-50

REMARKS: _____

Nº 5398

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 3/23 1950

RECEIVED OF W. D. Bryant

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED W. D. Bryant

TO TAP sanitary

SEWER, ON THE south

SIDE

OF Bennington NE

AVE.,
ST.,

TYPE OF STREET hard surface

THE PREMISES BEING LOT NO. 8387-1/2/8388

HOUSE NO. 1021

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR _____

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.