

Nº 5399

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 3-29-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 826

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 1' 6' deep



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Boger

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Milburn Rd. N.E.



SIGNED

John E. Chesser
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

4-4-50

REMARKS: _____

Nº 5399

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO,

3/25

1920

RECEIVED OF

Milbert M. Moss

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Milbert M. Moss

TO TAP

Sanitary

SEWER, ON THE

west

SIDE

OF

Milburn Ave

AGE
ST.

TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

8053

HOUSE NO.

826

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Dwain Bogen

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.