Nº 5406

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-3-30	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	: 3º North of Kondend, 6º Down
WAS LATERAL AT CURB? YES	NAME OF CONTRACTOR	bian a.
SHOW BY DIAGRAM RELATION OF LATI	ERAL TO WALL OF BUILDING	SERVED.
1974 ST. N.E	noortour-encymoptifications	5deep (
SIGNED INSPECTOR FOR CITY	FILED AT EN	NGINEER'S OFFICE 4-5-50
REMARKS:		

Nº 5406

PERMIT TO TAP SEWER

			4/4	
	an IA.	Massillon, Ohio,		194 0
RECEIVED OF	1.4 /120	ina	FEE OF \$	2 2
FOR WHICH PERMISSION	IS GRANTED (7. ()	Hlich	2	
10 TAP Danit	and sew	ER, ON THE	lant	SIDE
of 19 St	11/0	YPE OF STREET	vilou	
	51.,	_		
THE PREMISES BEING LOT	No. 9140-01	9/4/ HOUSE NO	414	, white the second second
		· .		
WORK TO BE DONE IN A	CCORDANCE WITH ORDINA	NCE NO. 2323. DULY P	ASSED BY THE CITY	COUNCIL, AND
RULES OF THE DEPARTME	ENT OF PUBLIC SERVICE.			e sequence of the
NAME OF CONTRACTOR	a. 0. 10	in a		

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.