N_{\cdot}^{0} 5413

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

ery Essa.	4			

DATE INSPECTED 4-11-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 233	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	81.	7. dech
WAS LATERAL AT CURB?		**	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	yogen	
SHOW BY DIAGRAM RELATION OF LATE	RAL TO WALL OF BUILDING S	SERVED.	
17. Telt 5 %	N E		18 Goday
	minimpeters and a constraint of constraint of constraints.	81 745	4/9
SIGNED INSPECTOR FOR CITY		BINEER'S OFFICE	20 octor of the annual communication and a com
REMARKS:			The state of the s

Nº 5413

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	Massillon, Ohio,	4/11	150
RECEIVED OF HE	an	FEE OF \$	2 -
FOR WHICH PERMISSION IS GRANTED	and M	engel	•
TO TAP Sanitary SEWE		west	SIDE
OF 17 11 11 8 AVE. TYP	PE OF STREET	oilea	
THE PREMISES BEING LOT NO. 9054	, House No.	233	
WORK TO BE DONE IN ACCORDANCE WITH OPDINANCE		LEGED BY THE CITY CO	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Dwam Bogen

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.