## Nº 5418

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-21-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 723	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? YES	NAME OF CONTRACTOR BOGEY
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LAT	NAME OF CONTROL OF THE PROPERTY OF THE PROPERT
	Foundation not laid
	not known - 18 Deep front Blog
	Back of W. Sidell. J. Deep Line locate
Main	Sewer -
DI Carlin	1-21-50
SIGNED INSPECTOR FOR CI	FILED AT ENGINEER'S OFFICE
REMARKS:	

## $N_{0}$ 5418

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	4/2
RECEIVED OF John Ohly	MASSILLON, OHIO, 1940
OR WHICH PERMISSION IS GRANTED James	Wrenche
<b>1</b>	, ON THESIDE
PORT LITH ME AVE. TYP	E OF STREET der
HE PREMISES BEING LOT NO. /4/6	
VORK TO BE DONE IN ACCORDANCE WITH ORDINANC ULES OF THE DEPARTMENT OF PUBLIC SERVICE.	E NO. 2323. DULY PASSED BY THE CITY COUNCIL, AND

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.