Nº 5422

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-9-50 HOUSE NO. 372 352	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	8' deap
WAS LATERAL AT CURB?	on new time for	om startinghoing
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR PIGHT	
	RAL TO WALL OF BUILDING SERVED.	To a second
272H 77 N.	W.	8
		1 - 4. Kay
na francisco con la ball	Language Control of the Control of t	1 /2
	- 1 fg	.91 - 8 deep
A CONTRACTOR OF THE PROPERTY O		
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	4-24-50
REMARKS:		**

BALANSENIE BANGLEBARE BENERALE AND A SERVICE OF THE DIRECTOR OF PUBLIC SERVICE

	PERMIT TO TAP SEWER
	MASSILLON, OHIO, 1950
	RECEIVED OF A Janu FEE OF \$ 200
\$ Sec. 1	FOR WHICH PERMISSION, IS GRANTED July Samuel
	OF 27 M AVE. TYPE OF STREET dut
	THE PREMISES BEING LOT NO. 326 - W. HOUSE NO. 193372
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323 DILLY DAGGED BY THE CITY CONTROL

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Of Juana

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.