36

Nº 5427

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-3-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	7 deep
WAS LATERAL AT CURB?		,
WAS ATTACHED TO MAIN 765	NAME OF CONTRACTOR Diana	
SHOW BY DIAGRAM RELATION OF LATE		
windson	Rd N.E.	
	6 deep	which the second
and the second s	N. S.	16 × 120 1
	September 1997 Septem	Mandaministration on many of the quality properties to the contract of the con
SIGNED SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE	territorium grafication de la companio de la compa
INSPECTOR FOR CIT		
REMARKS:	7	

RESTRICTED TO THE CALLET WIND AND TO OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

社画NY語法 3424 中 C Thair	PERMIT TO TAP SEWER
general de la companya de la company	MASSILLON, OHIO. 1950
RECEIVED OF	Juana FEE OF \$ 2 -
TO TAP Sarvitury	SEWER, ON THE SID
	AVE TYPE OF STREET
THE PREMISES BEING LOT NO. 249	9 , HOUSE NO. 1616

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A J. Gara

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.