

Nº 5433

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-1-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 915

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 29' 5'-6" Deep

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS: _____

6-2-3

5

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
CITY OF MASSILLON, OHIO
N^o 5433 PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/20 1950
RECEIVED OF John Astor FEE OF \$ 2.40

FOR WHICH PERMISSION IS GRANTED Arthur J. Astor

TO TAP San SEWER, ON THE East SIDE

OF Bennington AVE., TYPE OF STREET Local
ST.

THE PREMISES BEING LOT NO. 18537-38-34, HOUSE NO. 915

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Astor

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.