

Nº 5434

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-25-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 925

SIZE OF PIPE USED 6" 4/

DISTANCE FROM FIRST MANHOLE
~~DOWN~~ STREAM TO DITCH AT
CURB LINE AND DEPTH

87'

6' deep

WAS LATERAL AT CURB? yes

up stream.


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Bennington Ave. NE.



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS: _____

6-23

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o 5434 PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/20 1950
RECEIVED OF J. L. Aston FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Director Fisher

TO TAP San SEWER, ON THE P SIDE
OF Bennington AVE. TYPE OF STREET Alley
ST.

THE PREMISES BEING LOT NO. 18540-39, HOUSE NO. 925

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Aston

Note. This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health Regulations.