

Nº 5437

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED.

DATE INSPECTED 5-1-50

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_

HOUSE NO. 423

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH 4' 6' deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Astoria

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

26TH ST. N. W.

N →



SIGNED

John Ehrmer  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

5-31-50

MF

REMARKS: \_\_\_\_\_

7-415

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5437

# PERMIT TO TAP SEWER

MASSILLON, OHIO,

5/20

1950

RECEIVED OF

*H. Astor*

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

*Paul J. Renner*

TO TAP

*San*

SEWER, ON THE

*W.*

SIDE

OF

*26th NW*

AVE., TYPE OF STREET

*Wood*

THE PREMISES BEING LOT NO.

*8677*

HOUSE NO.

*423*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

*Astor*

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.