

Nº 5459

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

5-
48
✓

DATE INSPECTED 6-29-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 838

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

114'

7' deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Milburn Rd. N.E.

N →



SIGNED John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 7-1-50

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5459

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/27 1951

RECEIVED OF E. B. Mayo

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Donald W. Gray

TO TAP sanitary

SEWER, ON THE north

SIDE

OF Mulberry Park

AVE.
ST.

TYPE OF STREET dent

THE PREMISES BEING LOT NO. 8051

HOUSE NO. 838

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Diana

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.