

Nº 5469

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-15-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1008

SIZE OF PIPE USED 6

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 62' 8' deep



WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

32 ND ST. N.W.



SIGNED

John E. Hume
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7-6-50

REMARKS:

Lateral No-26 used

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5469

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/3 1920

RECEIVED OF R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED R. E. Painter

TO TAP San

SEWER, ON THE E

SIDE

OF 32nd

AVE.

TYPE OF STREET St.

THE PREMISES BEING LOT NO. 10212

HOUSE NO. 1008

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.