

Nº 5470

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 4-11-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1001

SIZE OF PIPE USED 6" 4/8 DISTANCE FROM FIRST MANHOLE
~~DOWN~~ STREAM TO DITCH AT 30'
CURB LINE AND DEPTH 8' deep


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Reinberg

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

32 ND ST. N.W.



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7-6-50

REMARKS:

Lateral No. 17 used

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5470

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/3 1950

RECEIVED OF R. Remy

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED R. C. Holmes

TO TAP San

SEWER, ON THE W

SIDE

OF 32nd W

AVE.,
ST.,

TYPE OF STREET dent

THE PREMISES BEING LOT NO. 4202

HOUSE NO. 1001

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remy

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.