

Nº 5478

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

5
30
✓

DATE INSPECTED 4-8-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 822

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

60' 8' deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

17TH ST. S.W.



Overlook Ave S.W.

SIGNED

John E. Egan
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7-21-50

REMARKS:

Sewer in Overlook Ave.

NOT FOR SALE

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 5478

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/3 1950

RECEIVED OF R. Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Chas Jitters

TO TAP San

SEWER, ON THE E

SIDE

OF 17th S.W.

AVE. ST.

TYPE OF STREET Alled

THE PREMISES BEING LOT NO. S.W. 8127

HOUSE NO. 822

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.