## Nº 5491

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-10-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	88.	7'deep
WAS LATERAL AT CURB?			
WAS ATTACHED TO MAIN / e	NAME OF CONTRACTOR	Diana	
SHOW BY DIAGRAM RELATION OF LATER	AL TO WALL OF BUILDING SE	RVED.	
22 NB 57 - 51			8
			- Chay
. A		•	. 6
<u> </u>	<b>&gt;</b>		3/
•	e e e e e e e e e e e e e e e e e e e	7484	
	5	7	110
		The second secon	The state of the s
	Windowskip in a security and a security of the	en e	$8.90 \mu / 3 \mu / 3$
SIGNED INSPECTOR FOR CITY	FILED AT EN	GINEER'S OFFICE	1 to my many
		rint in the second	
REMARKS:			

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 45491

## PERMIT TO TAP SEWER

MASSILLON, OHIO,	19 <b>50</b>
RECEIVED OF FEE OF \$	2 ~
FOR WHICH PERMISSION IS GRANTED . Mayo	
TO TAP Sanitary SEWER, ON THE West	SIDE
of 22 and le AVE. TYPE OF STREET dirt	
THE PREMISES BEING LOT NO. 4350 , HOUSE NO. 159	i version
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY OF	COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.	

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.