

10
10

Nº 5523

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 10-24-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 139

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 3' 6' 6" deep

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

1ST ST. N. W.



SIGNED

John E. Bremer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

10-25-50

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

NO. 5523

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/20 1924
 RECEIVED OF Hal Ruttledge FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Same

TO TAP San

SEWER, ON THE W

OF 1st

AVE., TYPE OF STREET Paup

THE PREMISES BEING LOT NO. 9177

HOUSE NO. 139

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Ramley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.