## 5526

## THERE'S TO BE FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED _//- / - 50 HOUSE NO / 8 4 8	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH  LINE AND DEPTH
WAS ATTACHED TO MAIN VES	NAME OF CONTRACTOR
LINDburgh,	RAL TO WALL OF BUILDING SERVED.
eneta lauti territgi la tiva kann kuti ilikuti dist kanka kanna	121. 65 Seep /5
SIGNED INSPECTOR FOR CIT	FILED AT ENGINEER'S OFFICE //-/3-50

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 5526 PERMIT TO TAP SEWER

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR COLOT

Note: This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.