

Nº 5528

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 11-10-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 806

SIZE OF PIPE USED 8"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 30 6' ditch



WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Diana

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Bernard Ave SW



SIGNED John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 7-20-50

REMARKS:

MEAS. OK.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5528

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/9, 1929

RECEIVED OF

G. J. Deana

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

H. J. Wagner

TO TAP

San

SEWER, ON THE

E

OF

Bernard St.

AVE., TYPE OF STREET

Alled

THE PREMISES BEING LOT NO.

4642

HOUSE NO.

806

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Deana

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.