FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 11-29-50	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 845	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH # dec./,
WAS LATERAL AT CURB?	NAME OF CONTRACTOR Smart + Harber
SHOW BY DIAGRAM RELATION OF LATE	Ave SE. 43
indo esna in rigne succesi i pro grama di M	
SIGNED INSPECTOR FOR CI	l myljerat je rominer si gelidiovi la sligar 🐣 🧦 🔭 🔭 🔻

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

And the second s
RECEIVED OF Amara to Harpen. FEE OF 50
FOR WHICH PERMISSION IS GRANTED Hames We Yours
TO TAP A SEWER, ON THE
of Herland 1 & AVE. TYPE OF STREET der
THE PREMISES BEING LOT NO. PA 1256 HOUSE NO. 845
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBLIC SERVICE

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.