

Nº 5538

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 3-17-51

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 909

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED _____


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Smart and Harber

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

JOHNSON ST. S.E.



SIGNED John Elmer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 3/28/51

REMARKS: Connected from house to garage in rear.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
Nº 5538 PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/6

RECEIVED OF

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.