

Nº 5541

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 6-3-56

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

OAK AVE. SE

CHURCH



SIGNED John E. Hanner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 1-24-51

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 5541

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/18, 1905

RECEIVED OF R. Remley

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED St. Matthews Church

TO TAP San

SEWER, ON THE

OF Oak St.

AVE., TYPE OF STREET Parish

THE PREMISES BEING LOT NO. 1015

HOUSE NO. 1015

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.