

Nº 5545

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 2-17-50

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 915

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 118' 7' deep



WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

1ST ST. N.E.



SIGNED John E. Brown

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 1-24-51

REMARKS: Re-laid job.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 5545

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/18 19

RECEIVED OF

R. Remley

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

J. W. Benson

TO TAP

San

SEWER, ON THE

W

OF

1st N E

AVE., TYPE OF STREET

Paved

THE PREMISES BEING LOT NO.

9716

HOUSE NO.

915

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.