Nº 5546

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

DATE INSPECTED 7-14-56	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 224	<u> </u>	
SIZE OF PIPE USED 67	DISTANCE FROM FIRST MANHOLE REMAIN STREAM TO DITCH AT CURB LINE AND DEPTH	5'doch
WAS LATERAL AT CURB?	en e	
WAS ATTACHED TO MAIN	- NAME OF CONTRACTOR Remle	4 .
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED. 🐪 🦯	1
Lincoln Way	C. W.	175
		1 4'degl
	Karana karangan da sebesah da seb	
ender til er en er til er er til til det skalle til det er ette skalle til til skalle til til skalle til skall Til skalle til skalle	(2) In the Carlo Carl	9
Verse		
	123	14 65 dech
SIGNED OF STATE STATES	FILED AT ENGINEEDS O	tapped in whatrea
REMARKS: Rear In 1	in a line of a to pine of political by	March - 24 - 51

THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER MASSILLON, OHIO, RECEIVED OF FOR WHICH PERMISSION IS GRANTED TO TAP SEWER, ON THE OF MARCH MAY LAVE., TYPE OF STREET ST., TYPE OF STREET

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR CONCRETE

Note. This permit covers work outside of building only. Any work it walls of building is subject to Massillon Board of Health Regulations.