### Nº 5555

# FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED.

1-1-50			V
DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 1441	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
SIZE OF PIPE USED 6" 0P	DISTANCE FROM FIRST MANHOLE DESCRIPTION DESCRIPTION DISTANCE FROM TO DITCH AT CURB LINE AND DEPTH	87	7' Deep.
WAS LATERAL AT CURBY YES	ignormalist of the second seco	A REPORT OF SECTION AND A	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	Remley	1
SHOW BY DIAGRAM RELATION OF LATER	RAL TO WALL OF BUILDING SE	RVED.	•
<ul> <li>Compared to the control of the control</li></ul>			
		Savisa iz ili izni siddi. Aztro Hs. (Volytti) Is	<b>V</b>
e en geste desentin som en de nodes som stendigener i	11 240 1	THE STATE OF THE SECTION OF THE SECT	N
	4 Deep by		s. Curb Line
· ·			
	9 87		\$ Sewer in Wal
SIGNED R. J. Windle	FILED AT EN	GINEER'S OFFICE	1 = Z 3 = 0° 0
INSPECTOR FOR CITY	grifficants of traidure of po		

#### THE CONTROL OF THE PROPERTY OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 5555 PERMIT TO TAP SEWER

the state of the s
MASSILLON, OHIO, // 0
RECEIVED OF A REMIDILY FEE OF \$0
FOR WHICH PERMISSION IS GRANTED DEMME My LUCO
Auni 1.
TO TAP SEWER, ON THE
of Walnut DW AVE., TYPE OF STREET Paul
THE PREMISES BEING LOT NO. 4773-73 , HOUSE NO. 1441
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCI
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.
Marin Ca.
NAME OF CONTRACTOR
and the first contract of the contract $m{J}$ . The contract of the contract $m{J}$

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.